Software Update - May 28, 2024

Semiconsoft, Inc. - TFCompanion release notes

Software update

- Fixed Modbus recipe-error handling so an exception raised by a wrong measurement recipe is cleared when the correct recipe is set.
- Fixed Modbus setFilmstack behavior after earlier PLC connector updates.
- Added software customization options for missing-license messages, Online menu visibility, registration tab visibility, and online Help menu visibility.
- Added getMemoryStatus to return free and used Java memory on the server.
- Added getConnectionAddress to return the IP address and port of the server connection.
- Added getRecipesList to return available measurement recipe names.
- Added getFilmstacksList to return available filmstack names.
- Added setMeasurementIntervalPLC to set the interval between measurements in milliseconds.
- Added support for UDP data-server output configured in PLC.properties.
- Added init_custom(ip, port), allowing both IP and port to be specified.
- Fixed Modbus.properties handling so both IP and port can be read from the properties file.